

THE FIGURES




Fig. 1 St Oswald's church, Crowle, site location




Fig. 2 St Oswald's Church Crowle, location of recorded areas




Fig. 3 composite of all the areas investigated inside the church




Fig. 5 North-west corner of the nave. Scale 1:20




Fig. 7. Nave north-east corner. Scale 1:20




Fig. 8 The north aisle